

PLASTIC PAD for evaporative cooling

Cleaning Instruction


The use of welded, highly resistant polymer sheets allows the Plastic Pad to be cleaned without difficulty and without damaging the Pads.

First step:

- Remove the dirty pad from the system

Second step:

- Place it on a firm surface that allows dirty water to drain away.



Third step:

- Use a high-pressure cleaner with a maximum pressure of 120 bar.
- Keep a distance of min. 15 cm.

